

DMSMS NOTICE

DIMINSHING MANUFACTURING SOURCES AND MATERIAL SHORTAGES

| | | | |
|--|---|--|--|
| 1. TITLE INTERNATIONAL RECTIFIER (IR) HIREL PRODUCT DISCONTINUANCE | | 2. DOCUMENT NUMBER FV5-D-10-0003 | |
| | | 3. DATE (Year, Month, Day) 19 JULY 2010 | |
| 4. MANUFACTURER NAME AND ADDRESS INTERNATIONAL RECTIFIER CORPORATION 205 CRAWFORD ST LEOMINSTER, MA 01453 UNITED STATES | | 5. MANUFACTURER POINT OF CONTACT (NAME) MANUFACTURER'S REPRESENTATIVE OR CSR | |
| | | 6. MANUFACTURER POINT OF CONTACT TELEPHONE 978-534-5776 | |
| 7. CAGE CODE (H4) 69210 | 8. MANUFACTURER FINAL ORDER DATE 30 JUNE 2010 | 9. MANUFACTURER PART NUMBER SEE DOCUMENT | 10. BASE PART SEE DOCUMENT |
| 11. DOCUMENT ORIGINATOR INTERNATIONAL RECTIFIER 205 CRAWFORD STREET LEOMINSTER, MA 01453 | | 12. GOVERNMENT PART NUMBER NOT AVAILABLE | 13. SPECIFICATION NUMBER NOT AVAILABLE |
| | | 14. TYPE DESIGNATOR NOT AVAILABLE | 15. MODEL NUMBER NOT AVAILABLE |
| | | 16. NATIONAL STOCK NMBR (NSN) SEE DATABASE | 17. DRAWING NUMBER NOT AVAILABLE |
| 18. COMMENTS INTERNATIONAL RECTIFIER (IR) HIREL HAS ANNOUNCED TO THE DEFENSE SUPPLY CENTER, COLUMBUS (DSCC) THE DISCONTINUANCE OF IR PART NUMBERS AND STANDARD MICROCIRCUIT DRAWING (SMD) PRODUCT LISTED HEREIN. THIS NOTICE IS THE RESULT OF NON-IR MANUFACTURED MICROCIRCUIT DIE AVAILABILITY. FOR FURTHER DETAILS ON LIMITED PRODUCT AVAILABILITY AND/OR ALTERNATE DEVICES, PLEASE CONTACT YOUR LOCAL MANUFACTURER'S REPRESENTATIVE OR CONTACT IR HIREL SERVICE DEPARTMENT AT (978) 534-5776. | | | |
| FOR GOVERNMENT AGENCIES USE ONLY | | | |
| 19. FEDERAL GOVERNMENT NAME AND ADDRESS NOT AVAILABLE | | 20. FEDERAL GOVERNMENT POINT OF CONTACT NAME NOT AVAILABLE | |
| | | 21. FEDERAL GOVERNMENT POINT OF CONTACT TELEPHONE NOT AVAILABLE | |
| 22. CASE NUMBER NOT AVAILABLE | 23. USER RESPONSE DEADLINE DATE NOT AVAILABLE | 24. ROUTING IDENTIFIER CODE NOT AVAILABLE | |
| 25. SOLUTION /STATUS CODE NOT AVAILABLE | 26. USERS NOT AVAILABLE | | |

DMSMS Parts List

| IR Part# | SMD# |
|-----------------|-----------------|
| OM1322N2M | 77034032A |
| OM1325N2M | 77034062A |
| OM1815N2M | 596288553012A |
| OM1815NMM | 59628855301NA |
| OM1815NTM | 5962-8855301TA |
| OM1815SRM | 596288553014A |
| OM1815STM | 59628855301UA |
| OM1840NCM | 5962-8952101ZA |
| OM1840NKM | 5962-8952101XA |
| OM1840SCM | 5962-8952101YA |
| OM1905N2M | 5962-88746012A |
| OM1905NMM | 5962-8874601NA |
| OM1905NTM | 5962-8874601TA |
| OM1905SRM | 5962-88746014A |
| OM1905STM | 5962-8874601UA |
| OM1915N2M | 5962-88748012A |
| OM1915NKM | 5962-8874801YA |
| OM1915NMM | 5962-8874801NA |
| OM1915NTM | 5962-8874801TA |
| OM1915SRM | 5962-88748014A |
| OM1915STM | 5962-8874801UA |
| OM3901SCB | 5962-8949002XH |
| OM3904SCB | 5962-8949005XA |
| OM3909SCB | 5962-8949001XA |
| OM3910NTM | 5962-8767501UX |
| OM3910SRM | 5962-87675014A |
| OM3910STM | 5962-8767501UA |
| OM3911STM | 5962-8767502UA |
| OM3914NKM | 5962-8774101XA |
| OM3914NTM | 5962-8774101TA |
| OM3914SRM | 5962-87741014A |
| OM3914STM | 5962-8774101UA |
| OM3958NMM | 5962-99531MNA |
| OM3958STM | 5962-99531MUA |
| OM7580SCM | 5962-0323701YA |
| OM7580SMM | 5962-0323701XA |
| OM7581SCM | 5962-0323702MZA |
| OM7581SMM | 5962-0323702MXA |
| OM7585ANMM | 5962-0323703MMA |
| OM7585ASRM | 5962-0323703MUA |
| OM7585ASTM | 5962-0323703MTA |
| OM7764ASCM | 5962-0323801MYA |
| OM7764ASMM | 5962-0323801MXA |