

DMSMS NOTICE

DIMINSHING MANUFACTURING SOURCES AND MATERIAL SHORTAGES

1. TITLE INTERNATIONAL RECTIFIER (IR) HIREL PRODUCT DISCONTINUANCE		2. DOCUMENT NUMBER FV5-D-10-0005	
		3. DATE (Year, Month, Day) 19 JULY 2010	
4. MANUFACTURER NAME AND ADDRESS INTERNATIONAL RECTIFIER CORPORATION 205 CRAWFORD ST LEOMINSTER, MA 01453 UNITED STATES		5. MANUFACTURER POINT OF CONTACT (NAME) MANUFACTURER'S REPRESENTATIVE OR CSR	
		6. MANUFACTURER POINT OF CONTACT TELEPHONE 978-534-5776	
7. CAGE CODE (H4) 69210	8. MANUFACTURER FINAL ORDER DATE 30 JUNE 2010	9. MANUFACTURER PART NUMBER SEE DOCUMENT	10. BASE PART SEE DOCUMENT
11. DOCUMENT ORIGINATOR INTERNATIONAL RECTIFIER 205 CRAWFORD STREET LEOMINSTER, MA 01453		12. GOVERNMENT PART NUMBER NOT AVAILABLE	13. SPECIFICATION NUMBER NOT AVAILABLE
		14. TYPE DESIGNATOR NOT AVAILABLE	15. MODEL NUMBER NOT AVAILABLE
		16. NATIONAL STOCK NMBR (NSN) SEE DATABASE	17. DRAWING NUMBER NOT AVAILABLE
18. COMMENTS INTERNATIONAL RECTIFIER (IR) HIREL IS ANNOUNCING THE DISCONTINUANCE AND DIMINISHING (LIMITED) SUPPLY OF THE IR PART NUMBERS / PRODUCT LISTED HEREIN. THIS NOTICE IS THE RESULT OF NON-IR MANUFACTURED MICROCIRCUIT DIE AVAILABILITY. FOR FURTHER DETAILS ON LIMITED PRODUCT AVAILABILITY AND/OR ALTERNATE DEVICES, PLEASE CONTACT YOUR LOCAL MANUFACTURER'S REPRESENTATIVE OR CONTACT IR HIREL SERVICE DEPARTMENT AT (978) 534-5776.			
FOR GOVERNMENT AGENCIES USE ONLY			
19. FEDERAL GOVERNMENT NAME AND ADDRESS NOT AVAILABLE		20. FEDERAL GOVERNMENT POINT OF CONTACT NAME NOT AVAILABLE	
		21. FEDERAL GOVERNMENT POINT OF CONTACT TELEPHONE NOT AVAILABLE	
22. CASE NUMBER NOT AVAILABLE	23. USER RESPONSE DEADLINE DATE NOT AVAILABLE	24. ROUTING IDENTIFIER CODE NOT AVAILABLE	
25. SOLUTION /STATUS CODE NOT AVAILABLE		26. USERS NOT AVAILABLE	

DMSMS Parts List

Part#
OM7812HP
COM7812T
OM7812AIH3
OM7812IH3
OM7630NMM
OM11633SCX
OM7912HP
COM7912T
OM7912IH3
OM7633NMM
OM7912SRM
OM13027STX
OM7905AHVSTM
OM7912AHVSTM
OM7915AHVSTM
OM7654SMP
OM13712SXX