

DMSMS NOTICE

DIMINISHING MANUFACTURING SOURCES AND MATERIAL SHORTAGES

1. TITLE IRF7F3704 Product Discontinuance		2. DOCUMENT NUMBER FV5-D-19-0009A	
		3. DATE (Year, Month, Date) 2019, 04, 02	
4. MANUFACTURER NAME AND ADDRESS International Rectifier, HiRel Products Inc 205 Crawford St. Leominster, MA 01453		5. MANUFACTURER POINT OF CONTACT (NAME) Manufacturer's Representative or Service Account Specialist	
		6. MANUFACTURER POINT OF CONTACT TELEPHONE (978) 534-5776	
7. CAGE CODE (H4) 69210	8. MANUFACTURER FINAL ORDER DATE Not Available	9. MANUFACTURER PART NUMBER See Herein	10. BASE PART N/A
11. DOCUMENT ORIGINATOR Paul Hebert Director of Quality Assurance		12. GOVERNMENT PART NUMBER N/A	13. SPECIFICATION NUMBER N/A
		14. TYPE DESIGNATOR N/A	15. MODEL NUMBER N/A
		16. NATIONAL STOCK NUMBER (NSN) N/A	17. DRAWING NUMBER N/A
18. COMMENTS Amendment: The DMSMS is being updated to add a second part number to the product discontinuance list. The added part number is IRF7E3704. International Rectifier HiRel Products (IR HiRel) is announcing the discontinuance of the products listed below. Note that a last time buy is not available. IRF7F3704 [20V, N-Channel MOSFET in a TO-205AF package] IRF7E3704 [20V, N-Channel MOSFET in a LCC-18 package] For further details on this product and change, please contact your local manufacturer's representative or contact IR HiRel Customer Service department at (978) 534-5776..			
<i>FOR GOVERNMENT AGENCIES USE ONLY</i>			
19. FEDERAL GOVERNMENT NAME AND ADDRESS		20. FEDERAL GOVERNMENT POINT OF CONTACT NAME	
		21. FEDERAL GOVERNMENT POINT OF CONTACT TELEPHONE	
22. CASE NUMBER	23. USER RESPONSE DEADLINE DATE	24. ROUTING IDENTIFIER CODE	
25. SOLUTION /STATUS CODE	26. USERS		