

INTERNATIONAL RECTIFIER

HiRel Products

September 28, 2006

End of Life Notification

Please note this is a revised notification. This notice is to inform you of the end of life of the following part numbers:

Obsoleted Part#	Probable Substitutes
COM150T	OM185STP
OM1322N2M	OM7603N2M
OM1323N2M	Contact factory
OM1325N2M	OM7603N2M
OM1327N2M	Contact factory
OM1805N2M	OM7805N2M
OM1805-03N2M	OM7805-03N2M
OM1812N2M	Contact factory
OM1912N2M	Contact factory
OM3910NTM	OM1850STM
OM3910SRM	OM1850SRM
OM3910STM	OM1850STM
OM3911STM	OM1850STM
OM3024STX	OM1850STM
OM7604STM	OM185STP
OM13481STX	OM185STM
OM7604STP	OM185STP
OM3030SCM	OM184-5SCM
OM3029SCM	OM184-15SCM
OM3730SCP	OM184-15SCP
OM11628SCP	OM184-15SCP

Obsoleted Part#	Probable Substitutes
OM3728SCP	OM184-5SCP
OM7605SCP	OM184-5SCP
OM11626SCP	OM184-5SCP
OM12061SCX	OM184-5SCM
OM3056SCB	OM184-15SCM
OM7628NMM	OM7623NMM
OM7628NMP	OM7623NMP
OM7662STM	OM185-5STM
OM7664STM	OM185-15STM
OMA7663SCP	OM184-12SCP
OM7662SCP	OM184-5SCP
OM7664SCP	OM184-15SCP
OM11186STX	OM1850STM
OM11344STM	OM185STM
OMA7604STM	OM185STM
OMA7604ST3	OM185STM
OM5262SAP	HFA35HB120C
OM5262SAT	HFA35HB120CSCX
OM3730SCM	OM184-15SCM
OM7607SCP	OM184-15SCP

*The information presented is intended to assist you in selecting International Rectifier Products. The information contained in our cross reference is based on the best estimate of other manufacturer's published information at the time we collected the data. International Rectifier recommends that you completely review our datasheet to ensure that our product meets the need of your application. International Rectifier is not

responsible for any incorrect or incomplete information. No information provided herein should be used in a manner which is adverse to International Rectifier.

International Rectifier will be no longer be offering the above part numbers due to the diminishing source of supply.

IR HiRel will continue to offer a wide range of voltage regulators and packaging that will meet the needs of our Military/Defense and space customers.

If you have any further questions or would like assistance in choosing a replacement part please contact your local manufacturer's representative or contact HiRel Services at (978)534-5776.

Thank you,
HiRel Services