


DMSMS NOTICE

DIMINISHING MANUFACTURING SOURCES AND MATERIAL SHORTAGES

1. TITLE ART2815T Product Discontinuance		2. DOCUMENT NUMBER FV5-D-21-0008A																												
		3. DATE (Year, Month, Date) 2021, 02, 03																												
4. MANUFACTURER NAME AND ADDRESS International Rectifier, HiRel Products Inc 2520 Junction Ave San Jose, CA 95134		5. MANUFACTURER POINT OF CONTACT (NAME) Manufacturer's Representative or Service Account Specialist																												
		6. MANUFACTURER POINT OF CONTACT TELEPHONE (408) 434-5000																												
7. CAGE CODE (H4) 52467	8. MANUFACTURER FINAL ORDER DATE Not Available	9. MANUFACTURER PART NUMBER See Herein	10. BASE PART N/A																											
11. DOCUMENT ORIGINATOR Granville Rains Quality Assurance Manager		12. GOVERNMENT PART NUMBER N/A	13. SPECIFICATION NUMBER N/A																											
		14. TYPE DESIGNATOR N/A	15. MODEL NUMBER N/A																											
		16. NATIONAL STOCK NUMBER (NSN) N/A	17. DRAWING NUMBER 5962-04237																											
18. COMMENTS International Rectifier HiRel Products is announcing the discontinuance of the products listed herein. These include all screening levels denoted by suffix /EM, /FM, /CH and /CK. Note that a last time buy will not be available. Description: 30W Total Output Power, 28 Vin with Triple Output DC-DC Radiation Hardened Converter in an ART package																														
																														
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 33%;">EOL Material PN</th> <th style="width: 33%;">SMD</th> <th style="width: 33%;">Replacement Material</th> </tr> </thead> <tbody> <tr><td>8270</td><td></td><td>Contact Factory</td></tr> <tr><td>8787</td><td></td><td>Contact Factory</td></tr> <tr><td>8863</td><td></td><td>Contact Factory</td></tr> <tr><td>10150SC</td><td></td><td>Contact Factory</td></tr> <tr><td>10151SC</td><td></td><td>Contact Factory</td></tr> <tr><td>10210FM</td><td></td><td>Contact Factory</td></tr> <tr><td>10284FM</td><td></td><td>Contact Factory</td></tr> <tr><td>ART2815T</td><td>5962-04234</td><td>M3GB280515T</td></tr> </tbody> </table>				EOL Material PN	SMD	Replacement Material	8270		Contact Factory	8787		Contact Factory	8863		Contact Factory	10150SC		Contact Factory	10151SC		Contact Factory	10210FM		Contact Factory	10284FM		Contact Factory	ART2815T	5962-04234	M3GB280515T
EOL Material PN	SMD	Replacement Material																												
8270		Contact Factory																												
8787		Contact Factory																												
8863		Contact Factory																												
10150SC		Contact Factory																												
10151SC		Contact Factory																												
10210FM		Contact Factory																												
10284FM		Contact Factory																												
ART2815T	5962-04234	M3GB280515T																												
For further details on this product and change, please contact your local manufacturer's representative or contact IR HiRel Customer Service department at (408) 434-5000.																														
FOR GOVERNMENT AGENCIES USE ONLY																														
19. FEDERAL GOVERNMENT NAME AND ADDRESS		20. FEDERAL GOVERNMENT POINT OF CONTACT NAME																												
		21. FEDERAL GOVERNMENT POINT OF CONTACT TELEPHONE																												
22. CASE NUMBER	23. USER RESPONSE DEADLINE DATE	24. ROUTING IDENTIFIER CODE																												
25. SOLUTION /STATUS CODE	26. USERS																													