



SYMBOL	INCHES		MILIMETERS	
	MIN.	MAX.	MIN.	MAX.
A	1.510	1.550	38.35	39.37
B	0.745	0.770	18.92	19.56
C	0.260	0.300	6.60	7.62
D	0.038	0.042	0.97	1.07
E	0.080	0.105	2.03	2.67
F	40° BASIC		40° BASIC	
G	0.500 BASIC		12.7 BASIC	
H	1.186 BASIC		30.12 BASIC	
J	0.593 BASIC		15.06 BASIC	
K	0.400	0.500	10.16	12.70
Q	0.151	0.161	3.64	4.09
R	0.980	1.020	24.89	25.91

- NOTES:
- 1.- DIMENSIONING AND TOLERANCING PER ASME Y14.5M-1994.
  - 2.- CONTROLLING DIMENSION: INCH.
  - 3.- DIMENSIONS ARE SHOWN IN INCHES.
  - 4.- TOLERANCES ARE  $\pm 0.010$  U.O.S.
  - 5.- SEE INDIVIDUAL DATA SHEETS FOR PIN ASSIGNMENTS.