

DMSMS NOTICE

DIMINSHING MANUFACTURING SOURCES AND MATERIAL SHORTAGES

1. TITLE INTERNATIONAL RECTIFIER (IR) HIREL PRODUCT DISCONTINUANCE		2. DOCUMENT NUMBER FV5-D-10-0001	
		3. DATE (Year, Month, Day) 14 OCTOBER 2009	
4. MANUFACTURER NAME AND ADDRESS INTERNATIONAL RECTIFIER CORPORATION 205 CRAWFORD ST LEOMINSTER, MA 01453 UNITED STATES		5. MANUFACTURER POINT OF CONTACT (NAME) MANUFACTURER'S REPRESENTATIVE OR CSR	
		6. MANUFACTURER POINT OF CONTACT TELEPHONE 978-534-5776	
7. CAGE CODE (H4) 69210	8. MANUFACTURER FINAL ORDER DATE NOT AVAILABLE	9. MANUFACTURER PART NUMBER SEE DOCUMENT	10. BASE PART SEE DOCUMENT
11. DOCUMENT ORIGINATOR INTERNATIONAL RECTIFIER 205 CRAWFORD STREET LEOMINSTER, MA 01453		12. GOVERNMENT PART NUMBER NOT AVAILABLE	13. SPECIFICATION NUMBER NOT AVAILABLE
		14. TYPE DESIGNATOR NOT AVAILABLE	15. MODEL NUMBER NOT AVAILABLE
		16. NATIONAL STOCK NMBR (NSN) SEE DATABASE	17. DRAWING NUMBER NOT AVAILABLE
18. COMMENTS INTERNATIONAL RECTIFIER (IR) HIREL HAS ANNOUNCED TO THE DEFENSE SUPPLY CENTER, COLUMBUS (DSCC) THE DISCONTINUANCE OF IR PART NUMBERS AND STANDARD MICROCIRCUIT DRAWING (SMD) PRODUCT LISTED HEREIN. THIS NOTICE IS THE RESULT OF NON-IR MANUFACTURED MICROCIRCUIT DIE AVAILABILITY. FOR FURTHER DETAILS ON LIMITED PRODUCT AVAILABILITY AND/OR ALTERNATE DEVICES, PLEASE CONTACT YOUR LOCAL MANUFACTURER'S REPRESENTATIVE OR CONTACT IR HIREL SERVICE DEPARTMENT AT (978) 534-5776.			
FOR GOVERNMENT AGENCIES USE ONLY			
19. FEDERAL GOVERNMENT NAME AND ADDRESS NOT AVAILABLE		20. FEDERAL GOVERNMENT POINT OF CONTACT NAME NOT AVAILABLE	
		21. FEDERAL GOVERNMENT POINT OF CONTACT TELEPHONE NOT AVAILABLE	
22. CASE NUMBER NOT AVAILABLE	23. USER RESPONSE DEADLINE DATE NOT AVAILABLE		24. ROUTING IDENTIFIER CODE NOT AVAILABLE
25. SOLUTION /STATUS CODE NOT AVAILABLE		26. USERS NOT AVAILABLE	

DMSMS Parts List

IR Part#	IR Part#	IR Part#	IR Part#	IR Part#	IR Part#	SMD#
COM7805T	OM13055STX	OM13291STX	OM3146STX	OM7633NMP	OM7805SRM	5962-87776012A
OM1021NTX	OM13092STX	OM13316NKX	OM3244SMM	OM7636SMM	OM7805SRP	5962-87776014A
OM11001STX	OM13100NMM	OM13317NKX	OM3416STM	OM7636SMP	OM7812AIHM	5962-8777601TA
OM11179SCX	OM13102NMM	OM13353SCX	OM3466STM	OM7639SMP	OM7812AIHP	5962-8777601UA
OM11181STX	OM13107STM	OM13373SRX	OM3682STM	OM7640SMM	OM7812IHM	5962-88747014A
OM11203STP	OM13108STM	OM13374SRX	OM3738STM	OM7643SMM	OM7812IHP	5962-8874701NA
OM11203STX	OM13110STM	OM13376SRX	OM3828STM	OM7643SMP	OM7812SRM	5962-8874701TA
OM11204STX	OM13128SCX	OM13538SMM	OM3854STM	OM7671NKM	OM7812SRP	5962-8874701UA
OM11205STX	OM1315STX	OM13582SRX	OM3905SCB	OM7671NKP	OM7912AIHM	5962-8949006HXA
OM11251STX	OM1316STX	OM13814STX	OM71585STM	OM7671NMM	OM7912AIHP	5962-8949006HXA
OM11301SXX	OM1322NMM	OM1610STM	OM71585STP	OM7671SMM	OM7912IHP	5962-8958701UA
OM11350STX	OM1322NTM	OM1805-03N2M	OM7501SCB	OM7671SMP	OM7912SRP	5962-9088501MUA
OM11351STX	OM1322SMM	OM1812N2M	OM7501SCP	OM7671STM	OM9380SDM	5962-9571101MMA
OM11475STX	OM1322STM	OM1812NTM	OM7501SMB	OM7671STP	OM9380SDP	5962-9571101MUA
OM11507SXX	OM1323NMM	OM1812SRM	OM7501SMP	OM7805-03N2M		7703403MA
OM11556SCX	OM1323NTM	OM1812STM	OM7505SC2	OM7805AHM		7703403NA
OM11600STX	OM1323STM	OM1836SCM	OM7505SC2	OM7805AIH1		7703403TA
OM11679NTX	OM1325NKM	OM1912NMM	OM7505SC3	OM7805AIH2		7703403UA
OM11688STX	OM1325NMM	OM1912NTM	OM7505SC3	OM7805AIH3		7703404NA
OM11699STX	OM1325NTM	OM1912SRM	OM7505SCP	OM7805AIHM		7703404TA
OM11720STX	OM1325SMM	OM1912STM	OM7505SMP	OM7805AIHP		7703404UA
OM11785NMX	OM1325SRM	OM2940-15STM	OM7603N2M	OM7805EAM		77034064A
OM11794STX	OM1325STM	OM2940-5SMP	OM7603STM	OM7805H1		7703406MA
OM11796STX	OM13260STM	OM2940-5STM	OM7603STP	OM7805HP		7703406NA
OM11798STX	OM13262STM	OM2990-5SMP	OM7612STM	OM7805IH1		7703406TA
OM11824STX	OM1327NMM	OM2990-5SRM	OM7612STP	OM7805IH2		7703406UA
OM11850NMX	OM1327NTM	OM2990-5SRP	OM7625NMM	OM7805IH3		7703406YA
OM13032STX	OM1327SMM	OM2990-5STM	OM7629NMM	OM7805IHM		7703408MA
OM13050SMP	OM1327STM	OM2990-5STP	OM7629NMP	OM7805IHP		7703408NA
OM13054STX	OM13285STX	OM3002SMM	OM7630NMP	OM7805N2M		7703408TA
						7703408UA