

# DMSMS NOTICE

DIMINSHING MANUFACTURING SOURCES AND MATERIAL SHORTAGES

1. TITLE <b>INTERNATIONAL RECTIFIER (IR) HIREL PRODUCT DISCONTINUANCE</b>		2. DOCUMENT NUMBER <b>FV5-D-10-0004</b>	
		3. DATE (Year, Month, Day) <b>19 JULY 2010</b>	
4. MANUFACTURER NAME AND ADDRESS <b>INTERNATIONAL RECTIFIER CORPORATION 205 CRAWFORD ST LEOMINSTER, MA 01453 UNITED STATES</b>		5. MANUFACTURER POINT OF CONTACT (NAME) <b>MANUFACTURER'S REPRESENTATIVE OR CSR</b>	
		6. MANUFACTURER POINT OF CONTACT TELEPHONE <b>978-534-5776</b>	
7. CAGE CODE (H4) <b>69210</b>	8. MANUFACTURER FINAL ORDER DATE <b>30 JUNE 2010</b>	9. MANUFACTURER PART NUMBER <b>SEE DOCUMENT</b>	10. BASE PART <b>SEE DOCUMENT</b>
11. DOCUMENT ORIGINATOR <b>INTERNATIONAL RECTIFIER 205 CRAWFORD STREET LEOMINSTER, MA 01453</b>		12. GOVERNMENT PART NUMBER <b>NOT AVAILABLE</b>	13. SPECIFICATION NUMBER <b>NOT AVAILABLE</b>
		14. TYPE DESIGNATOR <b>NOT AVAILABLE</b>	15. MODEL NUMBER <b>NOT AVAILABLE</b>
		16. NATIONAL STOCK NMBR (NSN) <b>SEE DATABASE</b>	17. DRAWING NUMBER <b>NOT AVAILABLE</b>
18. COMMENTS <b>INTERNATIONAL RECTIFIER (IR) HIREL IS ANNOUNCING THE DISCONTINUANCE OF IR PART NUMBERS / PRODUCT LISTED HEREIN. THIS NOTICE IS THE RESULT OF NON-IR MANUFACTURED MICROCIRCUIT DIE AVAILABILITY.</b>  <b>FOR FURTHER DETAILS ON LIMITED PRODUCT AVAILABILITY AND/OR ALTERNATE DEVICES, PLEASE CONTACT YOUR LOCAL MANUFACTURER'S REPRESENTATIVE OR CONTACT IR HIREL SERVICE DEPARTMENT AT (978) 534-5776.</b>			
<b>FOR GOVERNMENT AGENCIES USE ONLY</b>			
19. FEDERAL GOVERNMENT NAME AND ADDRESS <b>NOT AVAILABLE</b>		20. FEDERAL GOVERNMENT POINT OF CONTACT NAME <b>NOT AVAILABLE</b>	
		21. FEDERAL GOVERNMENT POINT OF CONTACT TELEPHONE <b>NOT AVAILABLE</b>	
22. CASE NUMBER <b>NOT AVAILABLE</b>	23. USER RESPONSE DEADLINE DATE <b>NOT AVAILABLE</b>	24. ROUTING IDENTIFIER CODE <b>NOT AVAILABLE</b>	
25. SOLUTION /STATUS CODE <b>NOT AVAILABLE</b>		26. USERS <b>NOT AVAILABLE</b>	

**DMSMS Parts List**

Part#	Part#	Part#	Part#	Part#	Part#
OM11803NTM	OM7905SRP	OM7509SCP	OM1188SCX	OM11186STX	OM7581SMP
OM11296STM	COM7915T	OM7509SC2	OM185-5STM	OM3029SCM	OM7581SCP
OM11494STX	OM1026STX	COM117T	OM185-5STP	OM3730SCM	OM7764ASCP
OM11689STX	OM11495STX	COM137T	OM185-5NMM	OM3730SCP	OM7764ASMP
OM11721STX	OM11690STX	OM12023STX	OM13694NMX	OM7607SCP	OM11577STX
OM11816STX	OM11722STX	OM11987STX	OM185-5NMP	OM11628SCP	
OM1409SCB	OM11755STX	OM7603ST3	OM11185STX	OM184SCM	
OM13442N2M	OM13496STM	OM7625NMP	OM1317STX	OM184SCP	
OM13737N2X	OM1799STM	OM11760STX	COM150T	OM11152SCX	
OM3550SCB	OM3831STM	OM11020STX	OMA7604STM	OM11358SCX	
OM7815N2M	OM7915AIHM	OM13030STX	OMA7604ST3	OM11686SCM	
COM7905T	OM7915AIHP	OM13115STX	OM11344STM	OM13026SCX	
OM1024STX	OM7915IHM	OM7611STM	OM3024STX	OM3764SCM	
OM11051STX	OM7915IHP	OM7611STP	OM7604STM	OM7622NMM	
OM11137STM	OM7915IH3	OM1676STX	OM13481STX	OM7622NMP	
OM13286STX	OM1409SCB	OM11763STX	OM7604STP	OM7648SMM	
OM7905AIHM	OM13104NMM	OM13052SCX	OM3030SCM	OM7648SMP	
OM7905AIHP	OM13693NMX	OM3031SCM	OM3728SCP	OM11000SAX	
OM7905IHM	OM7634NMM	OM3727SCM	OM7605SCP	OM11534SXZX	
OM7905IHP	OM7634NMP	OM7610SCP	OM11626SCP	OM13243STZX	
OM7905AHP	OM11506SXX	OM11631SCP	OM12061SCX	OMN185SMP	
OM7642SMP	OM11183STX	OM3028SCM	OM3056SCB	OM71584STP	
OM7905EA	OM7915SRM	OM3725SCM	OM7628NMM	OM71587STP	
OM13106NMM	OM7915SRP	OM3725SCP	OM7628NMP	OM11150STX	
OM7632NMM	OM13443N2M	OM7608SCB	OM7662STM	OM7585ANMP	
OM7632NMP	OM11668SCX	OM7608SCM	OM7664STM	OM7585ASTP	
OM11182STX	OM13053SCX	OM7608SCP	OMA7663SCP	OM7585ASRP	
OM11633SCX	OM3550SCB	OM11629SCP	OM7662SCP	OM7580SMP	
OM7905SRM	OM7509SCM	OM184-5SCP	OM7664SCP	OM7580SCP	