

DMSMS NOTICE

DIMINISHING MANUFACTURING SOURCES AND MATERIAL SHORTAGES

1. TITLE INTERNATIONAL RECTIFIER (IR) HIREL PRODUCT DISCONTINUANCE		2. DOCUMENT NUMBER <b style="color: red;">FV5-D-12-0002
		0. DATE (Year, Month, Date) 2011, Nov 28th
0. MANUFACTURER NAME AND ADDRESS INTERNATIONAL RECTIFIER CORPORATION 2520 JUNCTION AVENUE SAN JOSE, CA. 95134 UNITED STATES	1. MANUFACTURER POINT OF CONTACT (NAME) MANUFACTURERS REPRESENTATIVE OR CSR	
	2. MANUFACTURER POINT OF CONTACT TELEPHONE (408) 434-5000	
3. CAGE CODE (H4) 52467	4. MANUFACTURER FINAL ORDER DATE 2011, DECEMBER 31st	5. MANUFACTURER PART NUMBER SEE DOCUMENT
		6. BASE PART SEE DOCUMENT
1. DOCUMENT ORIGINATOR INTERNATIONAL RECTIFIER 2520 JUNCTION AVENUE SAN JOSE, CA. 95134		2. GOVERNMENT PART NUMBER NOT AVAILABLE 14. TYPE DESIGNATOR NOT AVAILABLE
		3. SPECIFICATION NUMBER NOT AVAILABLE 15. MODEL NUMBER NOT AVAILABLE

18. COMMENTS

INTERNATIONAL RECTIFIER (IR) HAS ANNOUNCED TO THE DEFENSE LOGISTICS AGENCY LAND & MARITIME (DLA) THE DISCONTINUANCE OF IR THE PART NUMBER AND STANDARD MICROCIRCUIT DRAWING (SMD) PRODUCT LISTED HEREIN. THIS NOTICE IS THE RESULT OF PRODUCT OBSOLESCENCE.

IR PART#	SMD#
AMR2803R3S	5962-0424501HXA
AMR2803R3S	5962-0424501HXC
AMR2805S	5962-0424601HXA
AMR2805S	5962-0424601HXC

IR PART#	SMD#
AMR2812S	NOT LISTED AS SMD
AMR2815S	NOT LISTED AS SMD
AMR2815T	NOT LISTED AS SMD
8664-(AMR2803R3S)	NOT LISTED AS SMD
8663-(AMR2805S)	NOT LISTED AS SMD
8869-(AMR2812S)	NOT LISTED AS SMD
10069SC-(AMR2808S)	NOT LISTED AS SMD

FOR FURTHER DETAILS ON LIMITED PRODUCT AVAILABILITY AND/OR ALTERNATE DEVICES, PLEASE CONTACT YOUR LOCAL MANUFACTURER'S REPRESENTATIVE OR CONTACT IR HIREL SERVICE DEPARTMENT AT (408) 434-5000.

	16. NATIONAL STOCK NUMBER (NSN) NOT AVAILABLE	17. DRAWING NUMBER NOT AVAILABLE
--	---	--

