

DMSMS NOTICE

DIMINISHING MANUFACTURING SOURCES AND MATERIAL SHORTAGES

1. TITLE IRHLC77214 Part ID		2. DOCUMENT NUMBER FV5-D-16-0003	
		3. DATE (Year, Month, Date) 2016, 01, 28	
4. MANUFACTURER NAME AND ADDRESS International Rectifier, HiRel Products Inc 205 Crawford St. Leominster, MA 01453		5. MANUFACTURER POINT OF CONTACT (NAME) Manufacturer's Representative or CSR	
		6. MANUFACTURER POINT OF CONTACT TELEPHONE (978) 534-5776	
7. CAGE CODE (H4) 69210	8. MANUFACTURER FINAL ORDER DATE Immediate	9. MANUFACTURER PART NUMBER See Herein	10. BASE PART N/A
11. DOCUMENT ORIGINATOR Paul Hebert Director of Quality Assurance		12. GOVERNMENT PART NUMBER N/A	13. SPECIFICATION NUMBER N/A
		14. TYPE DESIGNATOR N/A	15. MODEL NUMBER N/A
		16. NATIONAL STOCK NUMBER (NSN) N/A	17. DRAWING NUMBER N/A
18. COMMENTS <p>International Rectifier HiRel Products is announcing the discontinuance of the products listed herein. IR will continue to offer the HiRel IRHLC77214 series under a new part identification number.</p> <p>See Table 1 attached herein for part obsolescence and new replacements.</p> <p>The new part nomenclature signifies a change in SEE test performance. Refer to GIDEP FV5-C-16-0014 for further details.</p> <p>For further details on these products and change, please contact your local manufacturer's representative or contact IR HiRel Customer department at (978) 534-5776.</p>			
<i>FOR GOVERNMENT AGENCIES USE ONLY</i>			
19. FEDERAL GOVERNMENT NAME AND ADDRESS		20. FEDERAL GOVERNMENT POINT OF CONTACT NAME	
		21. FEDERAL GOVERNMENT POINT OF CONTACT TELEPHONE	
22. CASE NUMBER	23. USER RESPONSE DEADLINE DATE	24. ROUTING IDENTIFIER CODE	
25. SOLUTION /STATUS CODE	26. USERS		

Table 1 – part obsolescence

Parts # Obsoleted				
100kRAD				
IRHLC77214	IRHLF77214	IRHLQ77214	IRHLG77214	IRHLNM77214
IRHLC77214CDK	IRHLF77214SCS	IRHLQ77214SCS	IRHLG77214SCS	IRHLNM77214SCS
IRHLC77214CDV				
300kRAD				
IRHLF73214	IRHLF73214	IRHLQ73214	IRHLG73214	IRHLNM73214
IRHLF73214SCS	IRHLF73214SCS	IRHLQ73214SCS	IRHLG73214SCS	IRHLNM73214SCS
IRHLC73214CDV				
NEW PART # REPLACEMENT (ID / MARKINGS)				
100kRAD				
IRHLC7S7214	IRHLF7S7214	IRHLQ7S7214	IRHLG7S7214	IRHLNM7S7214
IRHLC7S7214CDK	IRHLF7S7214SCS	IRHLQ7S7214SCS	IRHLG7S7214SCS	IRHLNM7S7214SCS
IRHLC7S7214CDV				
300kRAD				
IRHLF7S3214	IRHLF7S3214	IRHLQ7S3214	IRHLG7S3214	IRHLNM7S3214
IRHLF7S3214SCS	IRHLF7S3214SCS	IRHLQ7S3214SCS	IRHLG7S3214SCS	IRHLNM7S3214SCS
IRHLC7S3214CDV				
Die	TO-39	LCC-28 Quad	MO-36AB	SMD0.2
				