

DMSMS NOTICE

DIMINISHING MANUFACTURING SOURCES AND MATERIAL SHORTAGES

1. TITLE HTA, HTB, HTC, HTH, HTM Product Discontinuance	2. DOCUMENT NUMBER FV5-D-19-0004
	3. DATE (Year, Month, Date) 2019, 02, 18

4. MANUFACTURER NAME AND ADDRESS International Rectifier, HiRel Products Inc 2520 Junction Ave San Jose, CA 95134	5. MANUFACTURER POINT OF CONTACT (NAME) Manufacturer's Representative or Service Account Specialist
	6. MANUFACTURER POINT OF CONTACT TELEPHONE (408) 434-5000

7. CAGE CODE (H4) 52467	8. MANUFACTURER FINAL ORDER DATE Not Available	9. MANUFACTURER PART NUMBER See Herein	10. BASE PART N/A
11. DOCUMENT ORIGINATOR Granville Rains Quality Assurance Manager		12. GOVERNMENT PART NUMBER N/A	13. SPECIFICATION NUMBER N/A
		14. TYPE DESIGNATOR N/A	15. MODEL NUMBER N/A
		16. NATIONAL STOCK NUMBER (NSN) N/A	17. DRAWING NUMBER N/A

18. COMMENTS
 International Rectifier HiRel Products is announcing the discontinuance of the products listed herein. Note that a last time buy will not be available.

HT20003R3S	HTA20012D	HTB2805SN	HTM27092S/EM
HT20005S	HTA20012D/EM	HTB2812D	HTM27092S
HT20012D	HTA20015D	HTB2812S	10021
HTA20003R3S	HTA20015D/EM	HTB2812SN	10022
HTA20003R3S/EM	HTA20015S	HTB2815D/EM	10158
HTA20005D	HTA20015SN	HTB2815D	10159
HTA20005D/EM	HTB2803R3S	HTB2815DN	10215
HTA20005DB	HTB2803R3SN	HTB2815S	10216
HTA20005S	HTB2805D	HTB2815SN	10253
HTA20005S/EM	HTB2805DN	HTH27022S/EM	10358
HTA20005SN	HTB2805S	HTH27022S	10359



For further details on this product and change, please contact your local manufacturer's representative or contact IR HiRel Customer Service department at (408) 434-5000.

FOR GOVERNMENT AGENCIES USE ONLY

19. FEDERAL GOVERNMENT NAME AND ADDRESS	20. FEDERAL GOVERNMENT POINT OF CONTACT NAME	
	21. FEDERAL GOVERNMENT POINT OF CONTACT TELEPHONE	
22. CASE NUMBER	23. USER RESPONSE DEADLINE DATE	24. ROUTING IDENTIFIER CODE
25. SOLUTION /STATUS CODE	26. USERS	