


DMSMS NOTICE

DIMINISHING MANUFACTURING SOURCES AND MATERIAL SHORTAGES

1. TITLE OMC506 Motor Controller Discontinuance		2. DOCUMENT NUMBER FV5-D-21-0011	
		3. DATE (Year, Month, Date) 2021, 04, 29	
4. MANUFACTURER NAME AND ADDRESS International Rectifier, HiRel Products Inc 205 Crawford St. Leominster, MA 01453		5. MANUFACTURER POINT OF CONTACT (NAME) Manufacturer's Representative or Service Account Specialist	
		6. MANUFACTURER POINT OF CONTACT TELEPHONE (978) 534-5776	
7. CAGE CODE (H4) 69210	8. MANUFACTURER FINAL ORDER DATE July 15, 2021	9. MANUFACTURER PART NUMBER See Herein	10. BASE PART N/A
11. DOCUMENT ORIGINATOR Paul Hebert Director of Quality Assurance		12. GOVERNMENT PART NUMBER N/A	13. SPECIFICATION NUMBER N/A
		14. TYPE DESIGNATOR N/A	15. MODEL NUMBER N/A
		16. NATIONAL STOCK NUMBER (NSN) N/A	17. DRAWING NUMBER N/A
18. COMMENTS International Rectifier HiRel Products (IR HiRel) is announcing the discontinuance of the products listed below. These include all part screening levels denoted suffix. OMC506 32V Three-Phase Brushless DC Motor Controller in a MP-3T package Obsolete Part ID # OMC506 OM11178MPX  Note that a last time buy is available. For further details on this product availability and change, please contact your local manufacturer's representative or contact IR HiRel Customer Service department at (978) 534-5776. Reference datasheets for additional part identifiers and descriptor information.			
FOR GOVERNMENT AGENCIES USE ONLY			
19. FEDERAL GOVERNMENT NAME AND ADDRESS		20. FEDERAL GOVERNMENT POINT OF CONTACT NAME	
		21. FEDERAL GOVERNMENT POINT OF CONTACT TELEPHONE	
22. CASE NUMBER	23. USER RESPONSE DEADLINE DATE	24. ROUTING IDENTIFIER CODE	
25. SOLUTION /STATUS CODE	26. USERS		