



August 25, 2005

To: International Rectifier HiRel Customers

Re: Obsolescence and Last Time Buy Product Offering

In an effort to eliminate some overlap in our product offerings, International Rectifier HiRel Products will be discontinuing the Omnirel COM parts program for voltage regulators. Attached is the list of products affected as well as suggested replacement part numbers.

For customers with programs unable to transition to the suggested replacements, we will be offering a last time buy opportunity extending to 09/30/2005. There will be a minimum purchase order quantity requirement for last time buys of 100 pieces.

Please contact your local manufacturing representative to arrange any last time purchases.

Mary Quezaire

Mary Quezaire
Director, HiRel Business Management
Components Product
233 Kansas St
El Segundo, CA 90245
Phone: ++1 310-726-8960
Fax: ++1 310-252-7754
e-mail: mquezai1@irf.com

COM Parts Program

| COM | COT Replacement | OM SMD Replacement | SMD PART # |
|------------|---------------------------|------------------------------|---------------------------------|
| COM117HVT | OM7620STP | OM1321STM | 7703402UA |
| COM117T | OM7602STP | OM1320STM | 7703401UA |
| COM137T | OM7603STP | OM1322STM | 7703403UA |
| COM7805T | OM7805IHP | OM1805STM | 5962-8778201UA |
| COM7812T | OM7812IHP | OM1812STM | 5962-8777601UA |
| COM7905T | OM2990-5STP | OM2990-5STM | 5962-9571101MUA |
| COM7912T | OM7912IHP | OM1912STM | 5962-8874701UA |
| COM7915T | OM2990-15STP | OM2990-15STM | 5962-9570901MUA |