

DMSMS NOTICE

DIMINISHING MANUFACTURING SOURCES AND MATERIAL SHORTAGES

1. TITLE International Rectifier (IR) HiRel Product Discontinuance		2. DOCUMENT NUMBER FV5-D-09-001	
		3. DATE (Year, Month, Date) 03/31/09	
4. MANUFACTURER NAME AND ADDRESS International Rectifier, HiRel 205 Crawford St. Leominster, MA 01453-2329		5. MANUFACTURER POINT OF CONTACT (NAME) Manufacturer's Representative or CSR	
		6. MANUFACTURER POINT OF CONTACT TELEPHONE (978) 534-5776	
7. CAGE CODE (H4) 69210	8. MANUFACTURER FINAL ORDER DATE Immediate	9. MANUFACTURER PART NUMBER SEE DOCUMENT	10. BASE PART SEE DOCUMENT
11. DOCUMENT ORIGINATOR International Rectifier, HiRel 205 Crawford St. Leominster, MA 01453 Soon Ng – Director of Service		12. GOVERNMENT PART NUMBER NOT AVAILABLE	13. SPECIFICATION NUMBER NOT AVAILABLE
		14. TYPE DESIGNATOR NOT AVAILABLE	15. MODEL NUMBER NOT AVAILABLE
		16. NATIONAL STOCK NUMBER (NSN) SEE DATABASE	17. DRAWING NUMBER NOT AVAILABLE

18. COMMENTS

International Rectifier (IR) HiRel has announced to the Defense Supply Center, Columbus (DSCC) the discontinuance of the Standard Microcircuit Drawing (SMD) product listed in Table I herein. This notice is the result of non-IR manufactured microcircuit die availability.

For further details on limited product availability and/or alternate devices, please contact your local manufacturer's representative or contact IR HiRel Service department at (978) 534-5776.

Table I

SMD Reference	IR PN
5962-87776015A	OM1812N5M
5962-87782012A	OM1805N2M
5962-87782015A	OM1805SRM
5962-87782016A	OM1805N5M
5962-8778201MA	OM1805SMM
5962-8778201NA	OM1805NMM
5962-8778201TA	OM1805NTM
5962-8778201UA	OM1805STM
5962-8778201YA	OM1805NKM
5962-88747015A	OM1912N5M
5962-8949003XA	OM3903SCB
5962-8958701NA	OM2940-5N5M
5962-8958701NA	OM2940-12N5M
5962-9088501MNA	OM2940-15N5M
5962-9570901MZA	OM2990-15N5M
5962-9571001MNA	OM2990-12N5M
5962-9571101MNA	OM2990-5N5M