

DMSMS NOTICE

DIMINISHING MANUFACTURING SOURCES AND MATERIAL SHORTAGES

1. TITLE IR Voltage Regulator Product Discontinuance		2. DOCUMENT NUMBER FV5-D-12-003	
		3. DATE (Year, Month, Date) 02/18/12	
4. MANUFACTURER NAME AND ADDRESS International Rectifier, A&D 205 Crawford St. Leominster, MA 01453		5. MANUFACTURER POINT OF CONTACT (NAME) Manufacturer's Representative or CSR	
		6. MANUFACTURER POINT OF CONTACT TELEPHONE (978) 534-5776	
7. CAGE CODE (H4) 69210	8. MANUFACTURER FINAL ORDER DATE Immediate	9. MANUFACTURER PART NUMBER See Table I	10. BASE PART NA
11. DOCUMENT ORIGINATOR Soon Ng Director of Services		12. GOVERNMENT PART NUMBER N/A	13. SPECIFICATION NUMBER N/A
		14. TYPE DESIGNATOR N/A	15. MODEL NUMBER N/A
		16. NATIONAL STOCK NUMBER (NSN) FSC 5962	17. DRAWING NUMBER See Table I
18. COMMENTS <p>International Rectifier (IR) HiRel Business Unit is announcing the discontinuance (replacement) of the Low-Drop-Out Voltage Regulator products listed in Table I herein. This notice is the result of new dedicated microcircuit/semiconductor die used in product design.</p> <p>For further details on these products and available alternate devices, please contact your local manufacturer's representative or contact IR HiRel Business Unit Service department at (978) 534-5776.</p>			
<i>FOR GOVERNMENT AGENCIES USE ONLY</i>			
19. FEDERAL GOVERNMENT NAME AND ADDRESS		20. FEDERAL GOVERNMENT POINT OF CONTACT NAME	
		21. FEDERAL GOVERNMENT POINT OF CONTACT TELEPHONE	
22. CASE NUMBER	23. USER RESPONSE DEADLINE DATE	24. ROUTING IDENTIFIER CODE	
25. SOLUTION /STATUS CODE	26. USERS		

Table 1 – List

OM96XX Series			
Obsoleted PN		Replacemement PN (1)	Replacement PN (2)
OMR9600SCP		IRUH33P183B1MP	IRUH330118BP
OMR9600SCK		IRUH33P183B1MK	IRUH330118BK
OMR9600SFP		IRUH33P183A1MP	IRUH330118AP
OMR9600SFK		IRUH33P183A1MK	IRUH330118AK
OMR9601SCP		IRUH33P253B1MP	IRUH330125BP
OMR9601SCK		IRUH33P253B1MK	IRUH330125BK
OMR9601SFP		IRUH33P253A1MP	IRUH330125AP
OMR9601SFK		IRUH33P253A1MK	IRUH330125AK
OMR9604SCP		IRUH33PA13B1MP	IRUH3301A1BP
OMR9604SCK		IRUH33PA13B1MK	IRUH3301A1BK
OMR9604SFP		IRUH33PA13A1MP	IRUH3301A1AP
OMR9604SFK		IRUH33PA13A1MK	IRUH3301A1AK
OMR9605SCP		IRUH50PA23B1MP	IRUH3301A2BP
OMR9605SCK		IRUH50PA23B1MK	IRUH3301A2BK
OMR9605SFP		IRUH50PA23A1MP	IRUH3301A2AP
OMR9605SFK		IRUH50PA23A1MK	IRUH3301A2AK
OMR9607SCP		IRUH50P253B1MP	
OMR9607SCK		IRUH50P253B1MK	
OMR9607SFP		IRUH50P253A1MP	
OMR9607SFK		IRUH50P253A1MK	
OMR9608SCP		IRUH50P333B1MP	IRUH330133BP
OMR9608SCK		IRUH50P333B1MK	IRUH330133BK
OMR9608SFP		IRUH50P333A1MP	IRUH330133AP
OMR9608SFK		IRUH50P333A1MK	IRUH330133AK